## Jazz Add-on ports and Accessories

JZ-xxx, MJ20-xxx, USB2-xxx



## General data

Storage temperature (no ice) Operation temperature Ingress Protection Relative huminity, no condensation

-20 ... 60 °C / -4 ... 140 °F 0 ... 50 °C / 32 ... 122 °F IP 20 / NEMA 1 10 ... 95 %



Technical approvals, conformities

Approvals CEUK